


The image shows a close-up of a blue sports floor, likely made of wood or a composite material. The surface is heavily scratched and worn, with many fine, light-colored lines visible. There are several dark, irregular patches and smudges scattered across the floor, particularly in the center and lower right. A thick blue line runs diagonally across the lower half of the image. A thin green line runs vertically along the right edge. A small, dark, vertical mark is visible near the top center, with a line pointing to it from the text 'Reste Klebestreifen'.

Reste Klebestreifen

**WRG-Bendorf
Zustand Sportboden**

20.03.2025

2